


WARNING

DISCONNECT POWER BEFORE RE-LAMPING OR WIRING THE FIXTURE READ ALL INSTRUCTIONS COMPLETELY BEFORE STARTING INSTALLATION.



- Caution and care must be supplied by the person(s) installing, operating and caring of this lighting fixture.
- This fixture is designed to be mounted on a correctly installed on 1/2-13 threaded rod secured to structure and standard round or
 octagon box or a through wiring box with a plaster frame. The box must be securely mounted to the structure of the building. The
 crossbar and hardware supplied should be used. directly mounting the fixture to the outlet box may make it impossible to
 correctly align the fixture.
- This fixture is supplied with a 16ft. aircraft cable .

NOTICE:

CALIFORNIA PROP 65: THIS LIGHTING FIXTURE CONTAINS CHEMICALS KNOWN TO THE STATE OF CALIFORNIA TO CAUSE CANCER, BIRTH DEFECTS, AND/OR OTHER REPRODUCTIVE HARM. WASH HANDS AFTER USE.

FIXTURE PREPARATION


1. Remove the fixture, parts and parts bag(s) from the carton.

NOTICE:

• Before discarding the carton, double check to make certain that all parts are found.

FIXTURE INSTALLATION

 Attach the heavy duty strap unto the junction box and fasten using the mounting screw. (The green screw should face the floor). ATTACH THE SAFETY CABLE TO THE BUILDING STRUCTURE OR BRACE. (See FIGURE-01.)



- 2. Remove the threaded ring from the screw collar loop. Fully thread the screw collar loop onto the nipple. Thread the hex nut onto the nipple and the nipple into the heavy duty strap. Place the canopy over the screw collar and against the ceiling. Adjust the nipple so that 1/4" of threads on the screw collar loop extend beyond the canopy. Tighten the hex nut against the heavy duty strap. Using the threaded ring, install the canopy. (See Figure 1.)
- **3.** Fasten the ground wire to the green or bare copper wire in the outlet box of the green screw on the heavy duty strap.

Never fasten the ground wire to the black or "hot" wire! Failure to follow this instruction could result in serious injury or death!


4. Fasten the fixture lead's hot wire to the black wire in the outlet box. Fasten the wires together with an approved fastener (wire nut) Starting about 1" below the fastener, tightly wrap the connection with electrical tape so that the connections seals the end of the fastener. NOTE: SPT hot wire is the one with the writings.




Make sure that there is no exposed wire or strands that could cause a dangerous short circuit!

Electrical tape Approved fastener (wire nut)

- 5. Connect the fixture lead's neutral wire to the white wire in the outlet box. Fasten the joined wires as in step 4. NOTE: SPT cord's neutral wire does not have any writings on it.
- **6.** Slide the canopy and screw collar ring up the chain and secure the canopy to the ceiling.(See Figure 2.)
- 7. Install the lamps. (type-B lamp)



- 8. Safely install glass on tip of leaves & bottom metal ball . (See Figure-02)
- 9. Restore power to the circuit breaker or fuse box.



R-HA37 293-08

ITEM ND.	Part ND.	DESCRIPTION
1	R-HA37-HRD	MOUNTING HARDWARE
2	R-HA37-CPY	CANDPY ASSEMBLY
3	R-HA37-CHN	CHAIN SET
4	R-HA37-CAC	SOCKET COVER
5	R-HA37-ESK	SECKET
6	R-HA37-GLS	GLASS

